

Audit Photo Report

R-Cloud-24058217



Factory gate



Factory name



Factory building



Raw materials warehouse

Q I M A Audit Photo Report 2024



Cutting



Sewing



Molding and Inspection



Packing



Finished goods warehouse



Fire hydrant and alarm

QIMA Audit Photo Report 2024




Emergency exit marked with exit sign and emergency light



Fire extinguishers



Evacuation indicator



Evacuation map



Hydrant testing



Toilet


Q I M A Audit Photo Report 2024



Drinking water



First aid box



BSCI COC publicized




Electronic attendance recorder



Suggestion box (placed at production entrance.)



Business license



Fire license



Structural license




Environmental license





Environmental license



Social insurance





Commercial injury insurance





Factory procedures

Attendance records (monthly OT exceeded 36 hours)




Payroll records

Factory Disclaimer




QIMA CoC


Signed CAP




Signed CAP




Signed CAP



Signed CAP



Signed CAP



Signed CAP



NC- Missing belt guard on sewing machines.

Q I M A Audit Photo Report 2024



NC-Sewing machine without finger guard.



NC-Sewing machine without needle guard.



NC-Cutting operator did not use earplugs.



NC-No tissue paper and soap in toilet